

IMPORTANT PRODUCT RECALL

TEXSON LED Digital Alarm Clock Model LED-16



We have become aware that the LED-16 TEXSON Digital Electric Alarm Clock, sold between August 11th 2009 and May 11th 2010 has a manufacturing defect. This defect may cause the clock to overheat and it could melt or start a fire, possibly leading to serious injury.

If you own a TEXSON Digital Alarm Clock, please check the model number on the underside of the clock. The model affected is the LED-16 and they were sold in the Roys (Wroxham) Ltd shops.

These may also have been sold by other retailers, if in doubt please contact them.

If you have a Texson LED digital alarm clock (Model LED-16), please stop using it immediately.

If you have purchased it from Roys (Wroxham) Ltd stores please return it to any Roys (Wroxham) Ltd store for a full refund of the purchase price.

If you have any queries please do not hesitate to contact Roys (Wroxham) Ltd on 01603 782131.

We wish to thank you for your co-operation and apologise for any inconvenience.